

**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 1. Equipment and debris on north side of location.**



**Photo 2. Example of stained soil on location.**

**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 3. Example of stained soil on location.**



**Photo 4. Trash and debris on north side of location.**



**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 5. Example of trash leaving location.**



**Photo 6. Overview of location from northeast corner looking west.**



**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 7. Overview of location taken from northeast corner facing southwest.**



**Photo 8. Overview of location from east side looking west.**





**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 9. Example of equipment stored on location.**



**Photo 10. Example of equipment stored on location.**



**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 11. Example of equipment stored on location.**



**Photo 12. Example of debris on location.**





Inspection Photos  
Location Name: Anderson 43-29  
Location ID: 313194



Photo 13. Weeds and vegetation in tank battery berm.



Photo 14. Example of 1 of 2 produced water tanks re labeled as livestock water.

**Inspection Photos**  
**Location Name: Anderson 43-29**  
**Location ID: 313194**



**Photo 15. 1 of 4 unmarked risers.**



**Photo 16. Example of trash on location, t posts identify 2 of 4 unmarked risers.**

