

# *Inspection Photos*

*Loc#448834*

*Operator: Sandridge*

*Inspection Number: 692401150*

*Inspection Date: 6/27/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Northeast.

June 27, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Grizzly Hebron. Loc#448834





Photo#2:  
Trash, debris on site; human generated. And debris Weeds.



Photo#3:  
Trash, debris on site; human generated. And debris Weeds.

June 27, 2019





Photo#4:  
Sediment migrating off-site from base of berm.




Photo#5:  
Sediment migrating off-site from base of berm.

June 27, 2019





Photo#6:  
Trash, debris on site.



Photo#7:  
Trash, debris on site

June 27, 2019





**Photo#6:**  
BMPs that are installed are ineffective.



**Photo#7:**  
BMPs that are installed are ineffective.

June 27, 2019