

Mesa E25-697

Location # 324389



Well sign installed.



Rat hole closed.

Mesa E25-697

Location # 324389



Mesa E25-697
Location # 324389



Barb wire fencing broken at separator and tank battery.



Barb wire fencing broken at separator and tank battery.

Mesa E25-697

Location # 324389



Barb wire fencing broken at separator and tank battery.

Barb wire fencing broken at separator and tank battery.