

# Inspection Photos

API: 05-071-07386

Operator: ARP PRODUCTION COMPANY  
WAPITI OPERATING LLC

Inspection Date: 7/19/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 7/19/2019

## Inspection Photos



**Photo 1.** There are numerous noxious weeds along the main road that have not been treated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 7/19/2019



## Inspection Photos



**Photo 2.** There is List B noxious weeds growing along the main & access road to the location. (Canada thistle shown in photo)

Corrective action was not performed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 7/19/2019



## Inspection Photos



**Photo 3.** Road appears to have been graded but no BMP's are installed. Corrective action was not completed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 7/19/2019



## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07386 | Date: 7/19/2019