

Inspection Photos

07/19/2019

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 453292
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 453292



Photo 1: Photo taken from the south end of the location, facing west. Photos 1-4 provide an overview of the location from west, northwest, northeast to east. Photos show the vegetation over the reclamation area.

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: MURFIN DRILLING COMPANY INC - 61650
Location ID: 453292



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 453292



Photo 5: Photo taken from the location. Photo shows vegetative germination/establishment on location. Location appears to be progressing towards COGCC 1000 series final reclamation requirements.



Photo 6: Photo taken from the access road. Photo shows reclamation in process.

Inspection Photos

Operator Name: MURFIN DRILLING COMPANY INC - 61650

Location ID: 453292



Photo 7: Photo taken from the access road. Photo shows reclamation in process.



Photo 8: Photo taken from the access road. Photo shows reclamation in process.