

Inspection Photos
Operator: BP America
Location/API #: 067-06357
Date: 7-11-2019



Photo 1. View of discharge point in the western project area. It appears gravel is being carried off of the well pad from high energy flows. This needs to be stabilized. Additionally approximately 200 musk thistles observed.



Photo 2. View of the southern project area from the southwestern edge facing eastward.