

# *Inspection Photos*

*Loc#458558*

*Operator: Sandridge*

*Inspection Number: 692401181*

*Inspection Date: 7/18/19*





Photo#1:  
Overview of Location to East. Note fugitive dust in insert.

July 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#2:  
Overview of Location to West. Arrow indicates grub/topsoil stockpile position.

July 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#3:  
View along silt fence where BMPs are needed.



Photo#4:  
View along silt fence where BMPs are needed.

July 18, 2019