

Inspection Photos

Loc#463987

Operator: Sandridge

Inspection Number: 692401182

Inspection Date: 7/18/19





Photo#1:
Overview of Location from road leading into site.

July 18, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#2:
Overview of Location from Southeast corner to entry at Northwest.

July 18, 2019



Photo#3:
Silt fence; perimeter and topsoil stockpile BMP.



Photo#4:
Silt fence; perimeter and topsoil stockpile BMP

July 18, 2019



Photo#5:
Culverts installed; sediment BMPs and silt fence repair needed.

Photo#6:
Culverts installed; sediment BMPs and silt fence repair needed.

July 18, 2019



Photo#7:
Material being tracked off Location.



Photo#8:
Crew cleaning material off entry.

July 18, 2019



Inspection Photos: Sandridge Marmot Loc#458558



Photo#9:
Fugitive Dust; water truck working.



Photo#10:
Fugitive Dust; water truck working

July 18, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558