

Inspection Photos

API: 071-07136

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 1. Facing toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 2. There is an electric powerline than travels to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 3. There is a 12" pipe with a sign that says "Receiver Tarantula 24-33".



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 4. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 5. There is an electric utility that remains at the location.



Inspection Photos



Photo 6. There is a perimeter ditch that diverts drainage around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019

Inspection Photos



Photo 7. Facing north at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 7/22/2019