

Inspection Photos

Location Name: SOONER UNIT-68N58W /28NWNE

Location #: 323461



Colorado Oil & Gas Conservation Commission
40.6381, -103.86572, 1428.0m, 360°
2018/11/16 02:54:00 PM

Photo #1

Sooner Unit 2-28 (05-123-13065) UIC Wellsite
Temporarily Abandoned | TA
prior insp.



Colorado Oil & Gas Conservation Commission
40.63813, -103.86535, 1421.0m, 274°
07/22/2019 01:12:37 PM

Photo #2

Sooner Unit 2-28 UIC Wellsite
Plugged & Abandoned | PA
≈ 15 yds.

Inspection Photos

Location Name: SOONER UNIT-68N58W /28NWNE

Location #: 323461



Photo #3
Sooner Unit 2-28 UIC Wellsite
Temporarily Abandoned | TA
Unused Equipment
prior insp.



Photo #4
Sooner Unit 2-28 UIC Wellsite
Plugged & Abandoned | PA
Most unused equipment removed.
Unused Electrical panel & pole needs removed.