

Inspection Photos
Location Name: NGL C10 & C10A
Location ID: 440290



Photo 1 – Facility Sign

Photo 2 – Tanks

Inspection Photos
Location Name: NGL C10 & C10A
Location ID: 440290



Photo 3 – C10 Wellhead Sign

Photo 4 – C10 Wellhead

Inspection Photos
Location Name: NGL C10 & C10A
Location ID: 440290



Photo 5 – C10A Wellhead Sign

Photo 6 – C10A Wellhead

Inspection Photos
Location Name: NGL C10 & C10A
Location ID: 440290



Photo 7 – Unused Equipment on the Eastside of location



Photo 8 – Unused metal siding on the Westside of location

Inspection Photos
Location Name: NGL C10 & C10A
Location ID: 440290



Photo 9 – Weeds on the Northside of Location

Photo 10 – Weeds on Wellheads