

Grand Mesa Operating CO, Salen 14-35
121-11045

Inspection #688305293

7/19/2019

Routine Inspection



Colorado Oil and Gas Conservation Commission
39.56612, -103.41574, 5141.1ft, 337°
07/19/2019 12:07:52 PM



Colorado Oil and Gas Conservation Commission
39.56833, -103.39831, 5091.9ft, 314°
07/19/2019 12:44:24 PM



Colorado Oil and Gas Conservation Commission
39.56833, -103.39834, 5095.1ft, 306°
07/19/2019 12:44:28 PM



Stuffing box leak
and cellar is filled
with oil.

Colorado Oil and Gas Conservation Commission
39.56829, -103.39833, 5085.3ft, 311°
07/19/2019 12:44:44 PM

Flowline



Colorado Oil and Gas Conservation Commission
39.5683, -103.39833, 5085.3ft, 49°
07/19/2019 12:46:02 PM



Colorado Oil and Gas Conservation Commission
39.56829, -103.39842, 5078.7ft, 7°
07/19/2019 12:46:17 PM



Colorado Oil and Gas Conservation Commission
39.56843, -103.39859, 5085.3ft, 124°
07/19/2019 12:46:48 PM



Colorado Oil and Gas Conservation Commission
39.56844, -103.39792, 5105.0ft, 79°
07/19/2019 12:49:17 PM




Colorado Oil and Gas Conservation Commission
39.56844, -103.39793, 5101.7ft, 92°
07/19/2019 12:49:21 PM



Pilot is on.

Colorado Oil and Gas Conservation Commission
39.56843, -103.39782, 5088.6ft, 17°
07/19/2019 12:50:03 PM



Colorado Oil and Gas Conservation Commission
39.56837, -103.39784, 5098.4ft, 205°
07/19/2019 12:50:13 PM



Colorado Oil and Gas Conservation Commission
39.56844, -103.39793, 5101.7ft, 150°
07/19/2019 12:49:27 PM



Colorado Oil and Gas Conservation Commission
39.56796, -103.39797, 5091.9ft, 42°
07/19/2019 12:52:12 PM



Colorado Oil and Gas Conservation Commission
39.56831, -103.39835, 5091.9ft, 170°
07/19/2019 12:44:33 PM



Colorado Oil and Gas Conservation Commission
39.56802, -103.39784, 5088.6ft, 219°
07/19/2019 12:51:04 PM



Colorado Oil and Gas Conservation Commission
39.56799, -103.39782, 5088.6ft, 220°
07/19/2019 12:51:10 PM



Colorado Oil and Gas Conservation Commission
39.56795, -103.39784, 5095.1ft, 235°
07/19/2019 12:51:18 PM



SE corner of tank
berms.

Colorado Oil and Gas Conservation Commission
39.5679, -103.39785, 5098.4ft, 323°
07/19/2019 12:51:26 PM



Colorado Oil and Gas Conservation Commission
39.5679, -103.39788, 5105.0ft, 343°
07/19/2019 12:51:34 PM




Valve leak on oil tank pipe near gate.



Colorado Oil and Gas Conservation Commission
39.56792, -103.39797, 5101.7ft, 17°
07/19/2019 12:51:53 PM



Colorado Oil and Gas Conservation Commission
39.56792, -103.39797, 5098.4ft, 27°
07/19/2019 12:52:05 PM



Colorado Oil and Gas Conservation Commission
39.56797, -103.39797, 5088.6ft, 50°
07/19/2019 12:52:16 PM