

**Inspection Photos**  
**Location Name: WORM 33-36**  
**API#: 05-071-06826**  
**INSP. #: 695101103**



**PHOTO 1: WELLHEAD**



**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: WORM 33-36  
API#: 05-071-06826  
INSP. #: 695101103



Colorado Oil & Gas Conservation Commission  
37.04035, -104.72884, 2303.0m, 56°  
2019/07/23 13:12:45

**PHOTO 3: ACTIVE ONGOING RELEASE AT WELLHEAD  
APPEAR TO BE GREATER 1 BBL PRODUCED WATER. NO  
CONTAINMENT. **IMEDIATELY CONTROL RELEASE, RESPOND  
TO SPILL AND CONTACT COGCC EPS STAFF AND FILE SPILE  
REPORT AS REQUIRED BY RULE 906. CA DATE 7-24-19.****



**PHOTO 4: PRODUCED WATER RELEASE TRAVELED TO THE  
SOUTH, SOUTHEAST OF LOCATION IMAGE SHOWS DISTANCE  
OF IMPACTED AREA APPROXIMATELY 74' LONG BY 4' WIDE.**



**Inspection Photos**  
**Location Name: WORM 33-36**  
**API#: 05-071-06826**  
**INSP. #: 695101103**



**PHOTO 5: IMAGE SHOWING PRODUCED WATER POOLING ON LOCATION ALONG THE IMPACTED AREA APPROXIMATELY 3" DEEP IN SPOTS.**



**PHOTO 6: IMAGE SHOWING PRODUCED WATER POOLING ON LOCATION ALONG THE IMPACTED AREA APPROXIMATELY 3" DEEP IN SPOTS.**



**Inspection Photos**  
**Location Name: WORM 33-36**  
**API#: 05-071-06826**  
**INSP. #: 695101103**



**PHOTO 7: IMAGE SHOWING PRODUCED WATER POOLING  
ON LOCATION ALONG THE IMPACTED AREA APPROXIMATELY  
3" DEEP IN SPOTS.**



**PHOTO 8: IMAGE SHOWING PRODUCED WATER POOLING  
ON LOCATION ALONG THE IMPACTED AREA APPROXIMATELY  
3" DEEP IN SPOTS.**