

Location Name: Grayhorse Operating, Inc. – Query # 1
Inspection Date: 07/05/2019



Photo # - 1



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 2



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 3



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 4

Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 5



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 6



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date:07/05/2019



Photo # - 7



Location Name: Grayhorse Operating, Inc. – Query # 1 Flowline Spill
Inspection Date: 07/05/2019



Photo # - 8

