

Inspection Date : 7/23/2019



Location entrance with battery sign



Injection wellhead

GUNNISON ENERGY LLC - 10515
API# 05-029-06076 SPAULDING PEAK 1294 #24-12 WDW
Inspection Date : 7/23/2019



Tank battery and filter housings



Filter housings inside secondary containment.