

Inspection Photos

07/23/2019

Operator: GRAND MESA OPERATING CO #
35080

Location ID: 466147
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 466147



Photo 1: Photos 1-4 taken from the east end of the location, facing south, southwest, northwest to north. Photos show construction in process. Photos also show surface roughening stormwater BMP has been installed along perimeter of the location/disturbance.



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 466147



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 466147



Photo 5: Photo taken from the north end of the location, facing northwest. Photo shows topsoil stockpile. Soil salvage in process at time of inspection. Stabilization BMPs will need to be installed to protect from stormwater/wind have not been installed in accordance with 1002.c



Photo 6: Photo taken from the southwest corner of the location, facing north. Photo shows construction in process. Photo also show surface roughening stormwater BMP has been installed along perimeter of the location/disturbance.



Inspection Photos

Operator Name: GRAND MESA OPERATING CO # 35080

Location ID: 466147



Photo 7: Photo taken from the southwest corner of the location, facing east. Photo shows construction in process. Photo also show surface roughening stormwater BMP has been installed along perimeter of the location/disturbance.



Photo 8: Photo taken from the access road entrance. Photo of cattle guard.