

Murphy 1-B
API: 05-103-05307
Inspection: 679704865



Photo 1. Pump jack location.



Murphy 1-B
API: 05-103-05307
Inspection: 679704865



Photo 3. Well head sign.



Photo 4. Weeds next to pump jack.

Murphy 1-B
API: 05-103-05307
Inspection: 679704865



Photo 5. Stained soil next to well head.