

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 1



Pic 2 separator with trash unused equipment

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 3 separator with no bird protector



Pic 4 unknown contents in drums behind separator, weeds around location

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 5 wellhead no sign



Pic 6 unused equipment on ground next to wellhead

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 7 unused 2" line going to pit



Pic 8 pit / weeds

Inspection Photos
Location Name: Linnebur 24-1
Location ID: 320225



Pic 9 pit fence



Pic 10 tank no sign, placard, berm in disrepair, no cap on line