

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



Pic 1



Pic 2 storage of equipment

**Inspection Photos**  
**Location Name: Simpson A 9**  
**Location ID: 319940**



**Pic 3 storage of equipment**



**Pic 4 unknown drum on location**

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



Pic 5



Pic 6 possible leak

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.99487, -103.83237, 4774.3ft, 9"  
07/24/2019 12:30:21



COLORADO OIL AND GAS CONSERVATION COMMISSION  
39.99487, -103.83239, 4777.7ft, 294"  
07/24/2019 12:30:27

**Pic 7 possible leak**

**Pic 8 possible leak bucket with unknown substance**

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



**Pic 9 possible leak**



**Pic 10 stained soil below valves/bucket with unknown substance**

**Inspection Photos**  
**Location Name: Simpson A 9**  
**Location ID: 319940**



**Pic 11 stained soil below valve**



**Pic 12 unused riser/stained soil**

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



**Pic 13 fiberglass tubing on pit berm**



**Pic 14 possible spill from tank**

**Inspection Photos**  
**Location Name: Simpson A 9**  
**Location ID: 319940**



**Pic 15 fiberglass tubing/trash around water tank**

**Inspection Photos**  
**Location Name: Simpson A 9**  
**Location ID: 319940**



**Pic 16 Trash by water tank**



**Pic 17 Possible hydrocarbons in pit/no netting**

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



**Pic 18 unused trailer on location**



**Pic 19 pit no netting**

**Inspection Photos**  
**Location Name: Simpson A 9**  
**Location ID: 319940**



**Pic 20 pit**



**Pic 21**

Inspection Photos  
Location Name: Simpson A 9  
Location ID: 319940



Pic 22

Pic 23