

# CC 0620-21 Pad Location # 335198



Sign starting to discolor and crack.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

# CC 0620-21 Pad

## Location # 335198



Weeds on location around separators and an abandoned flowline.



# CC 0620-21 Pad

## Location # 335198



**Weeds on location around separators and an abandoned flowline.**



**Weeds on location around separators and an abandoned flowline.**



# CC 0620-21 Pad Location # 335198



**Weeds on location around separators and an abandoned flowline.**



**Weeds on location around separators and an abandoned flowline.**

# CC 0620-21 Pad

## Location # 335198



**Cut slope behind tank battery is sloughing sediment over bmps.**



**Cut slope behind tank battery is sloughing sediment over bmps.**

