

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #1 Photo of battery sign at entrance to location



Photo #2 Photo at entrance to location.

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #3 Photo of tank battery



Photo #4 photo at wellheads

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #5 unused riser not marked or locked out /tagged out



**Photo #6 unused riser not locked out /tagged out
Trash inside of containment
Unused equipment in containment**

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #7 Holes in tank containment liner



**Photo #8 7 Holes in tank containment liner
Unused equipment inside containment**

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #7 Liner inside tank containment in need of maintenance



Photo #8 Liner inside tank containment in need of maintenance

Laramie Energy LLC
API # 05-077-08933
Inspection # 696600388



Photo #9 Trash inside containment
Unused riser left inside of containment



Photo #10 Soiled rag and plastic left laying on location