

Inspection Photos
Operator: BP America
Location/API #: 067-09960
Date: 7-19-2019



Photo 1. View of the western project area from the northwestern corner facing southward.



Photo 2. View of Russian knapweed (*Rhaponticum repens*) and musk thistles (*Carduus nutans*) at the well pad entrance.