

BEST IMAGE  
AVAILABLE

# WELL LOG



COMPANY Koch Exploration Company

SEC. 20 T. 24S R. 50W  
LOG. NW NE

FARM Snyder et al NO. 1


RIG. NO. 2

TOTAL DEPTH 5291

COMM. 8-3-73

COMP. 8-25-73

COUNTY Bent Co., Colorado



CONTRACTOR Rains & Williamson Oil Co., Inc.

## CASING

20	10
15	8 5/8" @ 450' w/ 175 sx. lightweight, 3% cc. &
12	6 125 sx. common, 3% cc.
13	5

ELEVATION

PRODUCTION D & A ✓


FIGURES INDICATE BOTTOM OF FORMATIONS

Lime and Shale	1080
Shale and Lime	1865
Lime and Shale	2090
Shale and Lime	5291
<u>Rotary Total Depth</u>	<u>5291</u>

State of KANSAS  
County of SEDGWICK } ss:

I, Wilson Rains, President of the Rains & Williamson Oil Co., Inc. ~~XXXXXX~~

upon oath state that the above and foregoing is a true and correct copy of the log of the Snyder et al #1 well.



Subscribed and sworn to before me this 30th day of August 19 73

Wilson Rains  
WILSON RAINS

Juanita M. Green  
NOTARY PUBLIC  
Juanita M. Green