

# Final Reclamation Inspection

July 22, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-12447

Inspection Document #: 697500383

Weld County, CO

SWNW Section 21 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SCHNEIDER #1  
API: 05-123-12447



**Photo 1.** Photo taken from the western location, facing Southeast. Appears the Operator has performed final reclamation activities; however, there is not sufficient establishment of desirable vegetative growth. Photo illustrates undesirable, weedy annual vegetation mostly consisting of Kochia. Operator shall perform additional reclamation activities.

Inspection Photos  
Location Name: SCHNEIDER #1  
API: 05-123-12447



**Photo 2.** Photo taken from the location illustrating no desirable vegetative growth, only undesirable, weedy annual growth of Kochia.

Inspection Photos  
Location Name: SCHNEIDER #1  
API: 05-123-12447



**Photo 3.** Reference photo taken along the southern perimeter of location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: SCHNEIDER #1  
API: 05-123-12447



**Photo 4.** Reference vegetation appears to be but not limited to Smooth brome and Alkali sacaton grass.