

Inspection Photos

Location Name: Federal 8-1

Location ID: 315308 Remediation ID: 11538

Inspection Date: July 23, 2019



Photo #1 – Aerial view of Federal 8-1. The white square represents the location of pit 104322 (GISOnline).



Photo #2 – Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal 8-1

Location ID: 315308 Remediation ID: 11538

Inspection Date: July 23, 2019



Photo #3 – View of the excavation looking south, the landfarm area can be seen in the background.



Photo #4 – View of the landfarm area looking southwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal 8-1

Location ID: 315308 Remediation ID: 11538

Inspection Date: July 23, 2019



Photo #5 – View of the cross threaded bull plug on the flowline attached to the well christmas tree.



Photo #6 – View of the unmarked, unused flowline riser.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources