

Inspection Photos

Location Name: Surprise Unit 2-08H Location ID 436801; REM 13074



Location Sign.



Excavation of cuttings, view to the east and southern extent of excavation on right side of photo.

Inspection Photos

Location Name: Surprise Unit 2-08H Location ID 436801; REM 13074



Looking north. Note darker discolored material in excavation.



Looking north.



Inspection Photos

Location Name: Surprise Unit 2-08H Location ID 436801; REM 13074



Darker discolored material had hydrocarbon odor.



Darker discolored material had hydrocarbon odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources