

**Inspection Photos**  
**Operator: Red Mesa**  
**Location/API #: 067-06124**  
**Date: 7-24-2019**



Photo 1. View of musk thistles and mustard debris within the southeastern project area.



Photo 2. View of risers remaining on PA location.



Photo 3. View of erosional channels forming near entrance to well pad.