

Final Reclamation Inspection

July 22, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-16090

Inspection Document #: 697500385

Weld County, CO

SENW Section 21 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SCHNEIDER #22-21
API: 05-123-16090



Photo 1. Photo taken from a portion of the access road, facing North. Operator has failed to perform final reclamation activities throughout the access road. Photo illustrates the access road with gravel and no evidence that final reclamation activities occurred. In addition, noxious weeds (Musk and Scotch thistle) were observed throughout portions of the access road and well location.

Inspection Photos
Location Name: SCHNEIDER #22-21
API: 05-123-16090



Photo 2. Photo taken from a portion of the access road, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SCHNEIDER #22-21
API: 05-123-16090



Photo 3. Photo taken from the western well location. Operator has failed to control and manage noxious weeds. Photo illustrates noxious weeds (Scotch thistle).