

Final Reclamation Inspection

July 22, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 327046

Inspection Document #: 697500387

Weld County, CO

NESW Section 21 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRAGG PM F #21-11
Location ID: 327046



Photo 1. Photo taken from the offsite associated tank battery, facing West. Appears the Operator has performed final reclamation activities; however, Operator has failed to control and manage noxious weeds (Scotch thistle).

Inspection Photos
Location Name: BRAGG PM F #21-11
Location ID: 327046



07.22.2019 13:05

Photo 2. Photo taken from a portion of the access road, facing South. Operator has failed to perform Final Reclamation activities on the access road.

Inspection Photos
Location Name: BRAGG PM F #21-11
Location ID: 327046



Photo 3. Photo taken from the well location, facing South. Appears the Operator needs to perform additional final reclamation activities as the well location lacks growth and is not reflective of reference areas.