

Inspection Photos

07/25/2019

Operator: MAGPIE OPERATING INC - 52530

Location ID: 401718

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: MAGPIE OPERATING INC - 52530
Location ID: 401718



Photo 1: Photo taken from the pits, facing north. Photo shows pit walls remain evident. There are areas of the pits and pit walls that remain bare, or vegetated by undesirable weedy plant species not reflective of the reference area. Vegetation observed in photo predominantly Kochia, and undesirable weedy annual.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: MAGPIE OPERATING INC - 52530
Location ID: 401718



Photo 3: Photo taken from the northwestern end of the battery/pits location, facing northeast. Photo shows large areas of the location that remain bare, or vegetated by undesirable weedy plant species not reflective of the reference area. Vegetation observed in photo predominantly Kochia, and undesirable weedy annual.



Photo 4: Photo taken from the north end of the battery/pits location, facing south. See comments under photo 3.

Inspection Photos
Operator Name: MAGPIE OPERATING INC - 52530
Location ID: 401718



Photo 5: Continued from photo 4. Photo taken from the north end of the location. Photo shows soil surface of areas of the location that have not achieved a uniform desirable perennial vegetative cover.