

# Inspection Photos

07/25/2019

Operator: BEREN CORPORATION - 7800

Location ID: 317052

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: BEREN CORPORATION - 7800  
Location ID: 317052



**Photo 1:** Photo taken from the well. Subsidence remains evident at the well location.



**Photo 2:** Continued from photo 1. Photo shows subsidence concerns remains evident at the well. 6 foot measuring stick for reference.



Inspection Photos  
Operator Name: BEREN CORPORATION - 7800  
Location ID: 317052



**Photo 3:** Photo taken from the well location, facing northwest. Photo shows crop establishment on the location is stunted, and not reflective of the reference area. Reclamation concerns remain evident.



**Photo 4:** Photo taken from the well location, facing west. Photo shows crop establishment on the location is stunted, and not reflective of the reference area. Reclamation concerns remain evident.

Inspection Photos  
Operator Name: BEREN CORPORATION - 7800  
Location ID: 317052



**Photo 5:** Photo taken from the well location, facing south. Photo shows crop establishment on the location is stunted, and not reflective of the reference area. Reclamation concerns remain evident.



**Photo 6:** Photo taken from the well location. Photo shows crop establishment on the location is stunted, and not reflective of the reference area. Reclamation concerns remain evident. Crop height on location seen in picture ~8-10 inches. 6 foot measuring stick for reference.



Inspection Photos  
Operator Name: BEREN CORPORATION - 7800  
Location ID: 317052



**Photo 7:** Photo taken from the adjacent reference area. Photo shows crop establishment on the location/disturbance area is not reflective of the reference. Crop height on location seen in picture ~24 inches. 6 foot measuring stick for reference.



**Photo 8:** Continued from photo 7.