

## Inspection Photos Location #432265



1 location



2 location





## Inspection Photos Location #432265



3 location



4 location





## Inspection Photos Location #432265



5 Staining picture from previous inspection



6 Staining still present



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources