

## Inspection Photos

Location Name: SOONER UNIT-68N58W /16SWSW

Location #: 323740



**Photo #1**  
**Sooner Unit 13-16 (05-123-13452) Wellsite**  
**Bradenhead NOT plumbed to surface**  
**Unused Equipment**  
*previous insp.*



**Photo #2**  
**Sooner Unit 13-16 Wellsite**  
**Prior Unused Equipment – Removed**  
**Recent Unused Equipment on site**

## Inspection Photos

Location Name: SOONER UNIT-68N58W /16SWSW

Location #: 323740



**Photo #3**

**Sooner Unit 13-16** Wellsite

**Unused Equipment - scrubber**



**Photo #4**

**Sooner Unit** Battery | Facility

*from recent insp.*