

Laramie Energy LLC
API # 05-077-09034
Inspection # 696600394



Photo #1 Photo of battery sign at entrance to location



Photo #2 Photo at entrance to location.

Laramie Energy LLC
API # 05-077-09034
Inspection # 696600394



Photo #3 Photo of tank battery



Photo #4 photo at wellheads

Laramie Energy LLC
API # 05-077-09034
Inspection # 696600394



Photo #5 Sediment moving off location on SE side of location. BMP needs maintenance or is failing



Photo #6 Sediment moving off location on SE side of location. BMP needs maintenance or is failing

Laramie Energy LLC
API # 05-077-09034
Inspection # 696600394



Photo #7 Erosion is evident along un-stabilized slope at the North side of location .



Photo #8 Erosion is evident along un-stabilized slope at the North side of location .

Laramie Energy LLC
API # 05-077-09034
Inspection # 696600394



Photo #9 Unused equipment left on location.



Photo #9 Unused equipment left on location.
Board and T-posts