

Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 1: Tank Battery



Photo 2: (North) Condensate tank with no labeling

Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 3: (South) Condensate tank with no labeling



Photo 4: (SW) Condensate tank with no labeling



Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 5: (NW) Condensate tank with no labeling



Photo 6: Stained soil (E) separator

Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 7: Stained soil (E) separator



Photo 8: Stained soil (middle) separator



Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 9: Stained soil (middle) separator/bucket with unknown contents



Photo 10: Stained soil (W) separator



Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 11: Stained soil (W) separator



Photo 12: Stained soil (E) separator



Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 13: Stained soil (middle) separator



Photo 14: Weeds on location



Inspection Photos
Location Name: Lind Battery
Location ID: 302373



Photo 15: Weeds on location