

Inspection Photos
Location Name: Larson/Hill Pad
Location ID: 302243



Photo 1: Tank Battery



Photo 2: H2O tank has placard and labeling

Inspection Photos
Location Name: Larson/Hill Pad
Location ID: 302243



Photo 3: Stained soil removed



Photo 4: Erosion present on location



Inspection Photos
Location Name: Larson/Hill Pad
Location ID: 302243



Photo 5: Erosion to location



Photo 6: Erosion to location



Inspection Photos
Location Name: Larson/Hill Pad
Location ID: 302243



Photo 7: Stained soil in separator house



Photo 8: Stained soil in separator house

