

Inspection Photos
Operator: Red Mesa
Location/API #: 067-05392
Date: 7-24-2019



Photo 1. View of perimeter wattle in the northern project area facing westward.



Photo 2. View of project area from the northern edge facing center. Wattles are largely functioning. Minor new erosion observed where wattles are not sufficient to de-energize surface flows.