

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #1

State 1 (13-36) (05-123-09934) Wellsite

Shut-In | SI

Weeds

Photo #2

State 1 (13-36) Battery

Weeds

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #3
State 1 (13-36) Lease road
Ruts from prior insp.



Photo #4
State 1 (13-36) Lease road
Ruts – appears mitigated

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #5
State 1 (13-36) Location E. side
Stormwater erosion
prior insp.



Photo #6
State 1 (13-36) Location E. side
Stormwater erosion - Remains

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #7
State 1 (13-36) Gas engine
Stained soil
prior insp.



Photo #8
State 1 (13-36) Gas engine
Stained soil – Appears mitigated

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #9
State 1 (13-36) Battery
Weeds



Photo #10
State 1 (13-36) Battery
Weeds

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #11
State 1 (13-36) Gas engine
Weeds - Trash



Photo #12
State 1 (13-36) Pit
Weeds

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Photo #13
State 1 (13-36) Treater
Weeds



Photo #14
State 1 (13-36) Treater
Wildlife protector screen does NOT appear on stack

Inspection Photos
Location Name: STATE-610N62W /36SWSW
Location #: 318773



Colorado Oil & Gas Conservation Commission
40.78623, -104.27491, 1520.0m, 260°
07/29/2019 02:12:54 PM

Photo #15
State 1 (13-36) Crude oil tanks
Stained soil – S. tank loadout