

Grand Mesa Operating CO, Nana Unit 1-16
073-06769

Inspection #688305368

7/28/2019

Drilling/Surface Cementing/BOP Inspection



Located at CR 109
and 3T.

Colorado Oil and Gas Conservation Commission
39.41825, -103.49156, 5347.8ft, 250°
07/28/2019 01:05:53 PM



Colorado Oil and Gas Conservation Commission
39.4353, -103.54883, 5367.5ft, 274°
07/28/2019 08:36:05 AM



Colorado Oil and Gas Conservation Commission
39.43519, -103.54873, 5351.1ft, 302°
07/28/2019 08:35:37 AM



Colorado Oil and Gas Conservation Commission

39.4354, -103.54986, 5331.4ft, 263°

07/28/2019 11:29:11 AM



Colorado Oil and Gas Conservation Commission
39.43521, -103.54927, 5360.9ft, 206°
07/28/2019 12:29:49 PM



Colorado Oil and Gas Conservation Commission
39.43519, -103.54873, 5351.1ft, 241°
07/28/2019 08:35:42 AM



Colorado Oil and Gas Conservation Commission
39.43474, -103.54942, 5364.2ft, 246°
07/28/2019 08:56:42 AM



Colorado Oil and Gas Conservation Commission
39.43473, -103.54937, 5364.2ft, 281°
07/28/2019 08:59:30 AM



Colorado Oil and Gas Conservation Commission
39.43548, -103.54923, 5400.3ft, 223°
07/28/2019 09:59:59 AM



Colorado Oil and Gas Conservation Commission
39.43532, -103.54923, 5357.6ft, 277°
07/28/2019 09:17:57 AM



Colorado Oil and Gas Conservation Commission
39.43547, -103.54901, 5364.2ft, 183°
07/28/2019 11:27:16 AM