


Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Battery sign at entrance.

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo #1 Photo at entrance on NW side of location.



Photo #2 Photo at entrance facing N of location

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo #3 Photo of tank battery

Photo #4 photo at wellheads

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



**Photo #5 Un-stabilized slope on East side of location.
Sediment moving off slope**

**Photo #6 Un-stabilized slope on East side of location.
Sediment moving off slope**

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



**Photo #7 Un-stabilized slope on North side of location.
Sediment moving onto location**

**Photo #8 Un-stabilized slope on North side of location.
Sediment moving onto location**

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo #9 Un-stabilized slope and berm on W side of location. Sediment moving off location. Vegetation being choke

Photo # 10 Un-stabilized slope and berm on S side of location. Sediment moving off location. Vegetation being choke

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo # 11 Un-stabilized slope and berm on SW side of location. Sediment moving off location. Vegetation being choke

Photo # 12 Sediment moving off un-stabilized slope on south side of location choking out vegetation.

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo # 13 BMP on SW corner of entrance to location needs maintenance. Sediment moving off location and down access road.



Photo # 14 . Vegetation not able to grow due to erosion sediment moving off un-stabilized slope at SW side of location.

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo # 15 BMP on SW corner of entrance to location needs maintenance. Sediment moving off location and down access road.



Photo # 16 BMP on SW corner of entrance to location needs maintenance. Sediment moving off location and down access road.

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600402



Photo #17 BMP on SW corner of entrance to location needs maintenance. Sediment moving off location and down access road.



Photo #18 Sediment moving off location and down access road to the south into a creek bed.