

Inspection Photos

Location Name: Lion Creek 4-16H Location ID 418853

Inspection Date: 7/29/2019



Photo 1 – Photo of southern excavated area on west edge of pad, looking south.



Photo 2 – Northern excavated area on west edge of pad looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Lion Creek 4-16H Location ID 418853

Inspection Date: 7/29/2019



Photo 3 – Photo of northern excavated area on west edge of pad looking north.



Photo 4 – Location of removed tank battery and source of spill on location. Looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Lion Creek 4-16H Location ID 418853

Inspection Date: 7/29/2019



Photo 5 – Photo of excavated area on east edge of pad.



Photo 6 – Surface area of pad scraped in areas around tank battery and treater building.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lion Creek 4-16H Location ID 418853
Inspection Date: 7/29/2019



Photo 7 – Stockpiles of impacted material placed on liner.



Photo 8 - Stockpiles of impacted material placed on liner.



Inspection Photos

Location Name: Lion Creek 4-16H Location ID 418853

Inspection Date: 7/29/2019



Photo 9 – Stockpiles of impacted material placed on liner.



Photo 10 - Stockpiles of impacted material placed on liner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources