

# Construction and Stormwater Inspection

July 29, 2019

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697500391

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Little Lady 21 /South Well Pad  
Location ID: 462919



**Photo 1.** Photo taken from the southern location, facing Northwest. Operator has only mobilized equipment to location. Stormwater BMP installation is next on the schedule.