

Interim Reclamation and Stormwater Inspection

July 29, 2019

Operator: SUNBURST INC- 83555

Location ID: 417959

Inspection Document #: 697500397

Weld County, CO

SESE Section 36 T11N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the entrance of the location. Operator sign appears to be in compliance with COGCC rules.

Inspection Photos
Location Name: Moonshine #36-11-65
Location ID: 417959



Photo 2. Photo taken from the entrance of the location, facing West. Photo illustrates Operator recently mowed Interim Reclamation areas.

Inspection Photos
Location Name: Moonshine #36-11-65
Location ID: 417959



Photo 3. Photo taken from the central location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: Moonshine #36-11-65
Location ID: 417959



Photo 4. Photo taken from the northern location, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: Moonshine #36-11-65
Location ID: 417959



Photo 5. Photo taken of the production water tank on location. Water tank capacity written on tank but hard to see; NFPA label not legible.