

Inspection Photos
Location Name: Drake II 18-40
Location ID: 418514



Photo 1: Wellhead




Photo 2: Stained soil removed



Inspection Photos
Location Name: Drake II 18-40
Location ID: 418514



Photo 3: Stained soil removed



Photo 4: Stained soil removed



Inspection Photos
Location Name: Drake II 18-40
Location ID: 418514



Photo 5: Stained soil removed

