

Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill

Location ID: #323972 & Spill/Release ID: 466240

Inspection Date: July 24, 2019



Photo #1 – Facility sign.

Photo #2 – Active dig and haul operations were ongoing during COGCC inspection.



Inspection Photos

Location Name: Gibson Gulch Unit 66S91W 29SWSW & Tank Battery Spill

Location ID: #323972 & Spill/Release ID: 466240

Inspection Date: July 24, 2019



Photo #3 – Wellhead and condensate AST.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources