

Inspection Photos

API: 05-073-06065

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 7/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 1. Facing north along the access road. Vegetation has established along areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 2. Facing northwest toward the location. Vegetation is establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 3. Facing south toward the location. Vegetation is establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 4. Facing east toward the location. Vegetation is establishing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 5. South of the location at: Lat/Long:38.79662,-103.65101. A chunk of cement remains at the battery site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019

Inspection Photos



Photo 6. South of the location at: Lat/Long:38.79662,-103.65101. A cement pad remains at the battery site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06065 | Date: 7/25/2019