

**Inspection Photos**  
**Location Name: Milton H Nelson Unit b #1**  
**Location ID: 336292**



**Photo 1 WH. WH sign faded not legible. Weeds around WH and PU base.**



**Photo 2 Weeds on location. Unused equipment: PU base and Electric control panel.**

**Inspection Photos**  
**Location Name: Milton H Nelson Unit b #1**  
**Location ID: 336292**



**Photo 3 Noxious weeds appear to be dead.**



**Photo 4 Weeds around WH. 2" flow line appears to be closed well is shut in.**