

Inspection Photos
Location Name: Colclasure #42-21
Location ID: 305962



Photo 1 WH sign. Appears production flow lines have been removed from WH.



Photo 2 unused equipment PU and parts lying on ground.