

Inspection Photos
Location Name: Federal 10-1
Location ID: 315286 Remediation ID: 12185
Date: July 23, 2019



Photo #2 – Aerial view of Federal 10-1 location. Pit ID 104323 location is marked by the green square.



Photo #2 – Location sign

Inspection Photos
Location Name: Federal 10-1
Location ID: 315286 Remediation ID: 12185
Date: July 23, 2019



Photo #3 – View of the pit excavation looking east.



Photo #4 – View of the landfarm looking south.

Inspection Photos
Location Name: Federal 10-1
Location ID: 315286 Remediation ID: 12185
Date: July 23, 2019



Photo #5 – View of the landfarm looking south.



Photo #6 – View of the load out valve with stained gravel.

Inspection Photos
Location Name: Federal 10-1
Location ID: 315286 Remediation ID: 12185
Date: July 23, 2019



Photo #7 – View of open port on upper section of 400 BBL condensate tank #80410.

