

Inspection Photos

Location Name: SOONER UNIT-68N58W /21NWNW

Location #: 323773



Photo #1

Sooner Unit 4-21 (05-123-13505) Wellsite

Bradenhead NOT plumbed to surface

Stained soil

Unused Equipment

prior insp.



Photo #2

Sooner Unit 4-21 Wellsite

Temporarily Abandoned | TA

Stained soil appears mitigated

Bradenhead NOW plumbed to surface

Recent Unused Equipment on site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SOONER UNIT-68N58W /21NWNW

Location #: 323773



Photo #3

Sooner Unit 4-21 Wellsite

Prior Unused Equipment - remains



Photo #4

Sooner Unit 4-21 Wellsite

**Unused Equipment – Recent
Fittings – Electric panel**

Inspection Photos

Location Name: SOONER UNIT-68N58W /21NWNW

Location #: 323773



Photo #5

Sooner Unit Battery | Facility

from recent insp.